

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Meander corner common to Sections 13 & 18 (on right bank of Nehalem River) T3N, R 8&9W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 20"x10"x7" (in place with MC on S face) from which a:

60" Cedar bears S20°E 7 lks.; now 42" stump, scribes and face rotted off.

72" Fir bears N58°W 42 lks.; now 72" stump, scribes MC visible, rest burnt off.

RESTORED

Var. 21½°E

Erected mound of stone on E. side of MC stone from which a:

6" Cedar N86°W 42.8 ft.; scribed T3N R9W S13 MC BT RS 359.



14" Alder bears S70°E 39.0 ft.; scribed in bark, T3N R8W S18 MC BT.

Oregon State Board of Forestry metal location poster on original 40" Cedar stump BT.

Set 4"x4"x60" white painted Cedar post 1.0' SE of stone.

Dated May 22, 1957.

Restored by *Richard Morris* under my direction.
Richard Morris, Transitman



Present and witnessed by Lloyd Geraths
Robert Sturm