

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Meander corner common to Sections 13 and 18 (on left bank of Nehalem River) T3N, R8&9W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 16"x10"x5" (in place MC visible) from which a:

- 9" Ash bears S86°W 46 lks.; now missing.
- 15" Ash bears S63°E 46 lks.; now missing.

RESTORED Var. 21½°E

Erected mound of stone on E side of MC stone, from which a:



- 20" Hemlock bears S33°W 90.9 ft.; scribed T3N R9W S13 MC BT RS 359. (This tree located on S edge Nehalem River Road)
- 14" Alder bears S47°E 16.8 ft.; scribed in bark, T3N R8W S18 MC BT.

Oregon State Board of Forestry metal location poster on 20" Hemlock BT.

Also poster on 8" Alder N80°W 18.5 ft.
Set 4"x4"x60" white painted Cedar post 2.0' NE

Dated May 22, 1957.

Restored by *Richard A. Morris* under my direction.
Richard A. Morris, Transitman



Present and witnessed by Lloyd Geraths
Robert Stumm