

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 16 and 21,
T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

14"x13"x10" stone (now downhill out of place, $\frac{1}{4}$ on face)
from which a:

12" Hemlock bears N18°W 23 lks.; now 20" uproot, face
unexposed;

12" Hemlock bears South 17 lks.; now 25" stump, scribes
 $\frac{1}{4}$ S visible, lower face unexposed.

RESTORED by L. W. Amort RE 2311, Dec. 17, 1954

Set original stone in place and erected mound of
stone around from which a:

19" Hemlock bears S14°E 80.0 ft.; now 20" uproot,
roots and root hole in place, scribes $\frac{1}{4}$ S21 BT
RE 2311 visible.

25" Hemlock bears N66°E 127.9 ft.; now 25" uproot with
OSBF metal location poster, scribes $\frac{1}{4}$ S16 BT
visible roots and root hole in place.

4"x4"x84" white painted Cedar post 1.5' NW now down
out of place.

RESTORED Var. 21 $\frac{1}{2}$ °E

Replaced original $\frac{1}{4}$ stone and erected mound of rock
around it from which a:

22" Hemlock bears S0°30'W 208.6 ft.; scribed $\frac{1}{4}$ S21
BT RS 359.


5" Hemlock bears N36°W 48.2 ft.; scribed $\frac{1}{4}$ S16 BT.

Oregon State Board of Forestry metal location poster on
22" Hemlock BT.

Reset above 4"x4"x84" white painted Cedar post 1.5' NW.

Dated May 22, 1957

Restored by Richard A. Morris under my direction.
Richard A. Morris, Transitman



Present and witnessed by Lloyd Geraths
Richard Morris