

CHAINS

REESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY
(See Official Plat)

One-quarter corner common to Sections 31 and 32, T1N, R6W, W.M.,
Tillamook County, Oregon.

ORIGINAL - (No evidence of original corner found)

REESTABLISHED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY 1/4 S31 S32 1956
RS 359," 34 inches in ground, in small mound of stone,
and from which a:

34" Fir bears S65°E 6.4 ft.; scribed 1/4 S32 BT RS 359.
62" Fir bears S87°W 40.0 ft.; scribed 1/4 S31 BT.

Set 4"x4"x60" white painted Cedar post 1 ft. SW of pipe.
Oregon State Board of Forestry metal location poster on 34" Fir BT.

Dated October 4, 1956.

Reestablished by Richard Morris under my direction.
Richard Morris, Transitman

Present and witnessed by Robert Sturm

ESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY
(See Official Plat)

Center one-quarter corner common to Section 31, T1N, R6W,
W.M., Tillamook County, Oregon.

B
see Corrections
Report Page
375

ESTABLISHED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY C 1/4 S31 1956 RS 359."
33 inches in ground between roots of 31" Hemlock, and from
which a:

51" Fir bears S11 1/2°E 99.8 ft.; scribed C 1/4 S31 BT RS 359.
31" Fir bears S43°W 79.4 ft.; scribed C 1/4 S31 BT.

Set 4"x4"x60" white painted Cedar post 2 ft. SE of pipe.
Oregon State Board of Forestry metal location poster on 31"
Hemlock N6°W 2.0 ft.

Dated October 4, 1956.

Established by Richard Morris under my direction,
Richard Morris, Transitman

Present and witnessed by Robert Sturm

