

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 27, 28, 33 and 34,
T. 1N, R. 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing found 1 1/2" iron pipe 2" above ground in place)
from which a:

5" Maple bears N52°W 53 lks.; now missing.

4" Maple bears N19°E 37 lks.; now missing.

4" Barberry bears S63°E 21 lks.; now missing.

19" Spruce bears S59 1/2°W 60 lks.; now 47" stump, portion of
scribe mark visible on partially exposed face.

RESTORED

Set 4 x 4 x 60" white painted Cedar post 1.5 ft. NW of above
1 1/2" pipe from which a:

33" Hemlock bears N60°E 93.9 ft.; scribed TLN R9W S27
BT RS 359.

18" Spruce bears S25°W 26.3 ft.; scribed TLN R9W S33 BT.



23" Hemlock bears S55°E 110.4 ft.; scribed TLN R9W S34 BT.

Oregon State Board of Forestry metal location poster on
18" Spruce BT.

Oregon State Board of Forestry metal location poster on
4"x4"x72" white painted Cedar post 330 ft. S. on S. edge of
road.

Dated October 31, 1956.

Restored by Richard A. Morris under my direction.
Richard A. Morris, Transitman



Present and witnessed by Lloyd Geraths
Robert Sturm