

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 1, 2, 35 and 36  
T. 3 & 4 N, R. 8W, W.M., Tillamook & Clatsop  
County, Oregon.

ORIGINAL

Basalt stone 16" x 8" x 7" (now 5"x6"x8" with 5 notches  
on one side and one on other, out of place) from which a:

- 30" Fir bears N61° 45'E 31 lks.; now 30" snag, scribes  
T4N R8W S36 visible on charred face.
- 72" Fir bears S37°E 20 lks.; now 66" snag, scribes  
T3N R8W S visible on pieces of face lying on  
ground under rotted out face.
- 8" Maple bears S73°W 78 lks.; now missing, Maple  
clumps in vicinity.
- 30" Fir bears N27½°W 36 lks.; now 38" snag, edges of  
rotted out face visible, no scribes remaining.

RESTORED

Set original stone in place, with 5 notches on W. face  
and 1 on E, 5 inches in ground, in mound of stone,  
and from which a:



- 13" Fir bears S68½°W 16.0 ft.; scribed T3N R8W S2 BT.
- 14" Fir bears N49°W 11.6 ft.; scribed T4N R8W S35 BT.
- 26" Fir bears N18°E 19.4 ft.; scribed T4N R8W S36 BT RS 359.
- 12" Fir bears S59°E 21.0 ft.; scribed T3N R8W S1 BT.

Oregon State Board of Forestry metal location poster on  
26" Fir BT.

Set 4"x4"x72" white painted Cedar post 1 ft. NE of  
stone corner.

Dated November 1, 1956

Restored by Richard Morris under my direction.  
Richard Morris, Transitman



Present and witnessed by Lloyd Geraths  
Robert Sturm