

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 8 and 9, T3S, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 30" dead fir stub bears N42°E 25 lks.; now 39" x 30" high snag scribes $\frac{1}{4}$ S BT facing N74°W
- 48" fir bears N43 $\frac{1}{2}$ °W 27 lks.; now burnt out stump, log on ground.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S8 S9 1957 RS 359," 33 inches in ground, and from which a:



- 25" Fir bears N61°E 23.7 ft.; scribed $\frac{1}{4}$ S9 BT.
- 60" Fir bears N14 $\frac{1}{2}$ °W 54.7 ft.; scribed $\frac{1}{4}$ S8 BT RS 359.

Oregon State Board of Forestry metal location poster on Original 30" Dead fir.

Set 3"x3"x48" white painted Cedar post 1 ft. NW of pipe.

Dated April 12, 1957.

Restored by



Present and witnessed by Richard Morris
Lloyd Geraths
Robert Sturm