

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 26, 27, 34 and 35 T. 2N., R. 8W., W.M., Tillamook County, Oregon.

ORIGINAL

17" x 12" x 5" stone (found in place with 1 notch on S. and 2 on E. faces) from which a:

4" Hemlock bears N.50°E. 18 lks.; now missing.

40" Larch bears S.20°E. 31 lks.; now 48" stub 10" high, scribes BT visible.

12" Hemlock bears S.70°W. 55 lks.; now just roots remaining in place.

8" Hemlock bears N.22°W. 40 lks.; now 10" uproot, roots in place, edges of burnt out face visible.

RESTORED

Var. 21-1/2°

Erected mound of stone around original cornerstone, from which a:

10" x 20" rock outcrop bears N.48°W. 32.5 ft.; scribed XBO.

49" Fir snag bears S.88 1/2°W. 49.1 ft.; scribed T2N R8W S34 BT.

46" Fir snag bears N.87°E. 45.6 ft.; scribed T2N R8W S26 BT.

32" Fir snag bears S.63°E. 16.7 ft.; scribed T2N R8W S35 BT RS40L.

Set 4" x 4" x 60" white painted cedar post 1.0" N.E. of pipe. Oregon State Board of Forestry metal location poster on 32" Fir snag B.T.

Also posted on 20" Fir stump approx. 30 chs. N. on N. edge Rd.

Dated June 5, 1957

Restored by



Richard A. Morris



Present and witnessed by Robert Sturm
Craig Chambers