

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 23 and 26, T. 2 N., R. 8W., W.M., Tillamook County, Oregon

ORIGINAL

12" x 12" x 8" Basalt stone (missing) from which a:

- 16" Hemlock bears South 27 lks.; now 18" stub, 5' high, scribes SB remaining, rest burnt out.
- 30" Hemlock bears N. 7° W. 40 lks.; now just root stub 1' high, face rotted off.

RESTORED

Var. 21-1/2° E.

Set 1-1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S23 S26 1957 RS 401," 33 inches in ground, in mound of stone, and from which a:


- 42" Fir snag bears S. 40° W. 45.8 ft.; scribed 1/4 S26 BT.
- 58" Fir stump bears N. 5° W. 58.7 ft.; scribed 1/4 S23 BT RS 401.

Oregon State Board of Forestry metal location poster on 58" fir stump B.T.


Set 3" x 3" x 60" white painted cedar post 1.5' S.W.

Dated June 17, 1957

Restored by



Richard A. Morris



Present and witnessed by Lloyd Geraths
Frank Dimmitt
Ron Fox