

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 1, 2, 11 and 12, T. 2N., R. 9W., W.M., Tillamook County, Oregon.

ORIGINAL

12" x 12" x 8" stone (now downhill out of place) from which a:

- 10" Hemlock bears N.57°W. 68 lks.; now 29" snag, scribes T. 2N., R. 9W. visible
- 8" Hemlock bears N.49°E. 37 lks.; now 6" uproot, roots in place, face rotted off.
- 9" Cedar bears S.21°E. 32 lks.; now 10" uproot, roots in place, face rotted off.
- 8" Hemlock bears S.44°W. 51 lks.; now 10" uproot, root hole in place, face burnt off.

RESTORED

Var. 21-1/2° E.


Set original corner stone in place with 5 notches on S., and 1 on E. faces, 6 inches in ground, in mound of stone and from which a:

- 56" Fir stump bears N.4°W. 31.7 ft.; scribed T 2N. R. 9W. S2 BT.
- 66" Fir stump bears S.81°W. 36.0 ft.; scribed T 2N. R. 9W. S11 BT RS401.
- 59" cedar stump bears N.4°E. 10.2 ft.; scribed T 2N. R. 9W. S1 BT.
- 60" Fir snag bears S.51 1/2° E. 31.0 ft.; scribed T 2N., R 9W. S12 BT.


Oregon State Board of Forestry metal location poster on 60" Fir snag BT.  
Set 4" x 4" x 60" white painted cedar post 1.0' S.E. of corner stone.

Dated June 14, 1957

Restored by



*Richard A. Morris*



Present and witnessed by Craig Chambers

BOOK 2