

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Base line Section corner common to Sections 35 and 36,  
T.1N., R.7W., W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing, road through point) from which a:

- 20" Hemlock bears S2°E 37 lks.; now 30" stump,  
scribes R7W T1S S1 visible.
- 10" Hemlock bears S52°E 31 lks.; now missing, point  
falls in road.
- 12" Hemlock bears N63°W 16 lks.; now 16" stub 7'  
high, now bears S63°W, knocked out of place by  
cat, scribes R1W T7N S2 visible.
- 18" Hemlock bears N13°W 21 lks.; now missing, point  
falls in road.

RESURVEY of base line 1884.  
(No trace of resurvey work found).

RESTORED



Set 1½" x 36" galvanized iron pipe with 3" bronze cap  
marked "OREGON STATE BOARD OF FORESTRY TLN R7W BL S35 S36  
S1 1957 RS359," 8" below surface of road, and from which a:

- 36" Fir stump bears N76°E 38.2 ft.; scribed TLN  
R7W S36 BT RS359.
- 39" Fir stump bears N37°W 142.0 ft.; scribed TLN  
R7W S35 BT.

Oregon State Board of Forestry metal location poster on 36"  
Fir stump BT.  
Also poster on 4" x 4" x 60" white painted cedar post 11.3' W  
on W. edge of road.

Dated May 28, 1957.

Restored by



Present and witnessed by Richard Morris, Robert Sturm, Craig Chambers