

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 12 and 13,
T.1S., R.9W., W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

24" Hemlock bears S64 $\frac{1}{2}$ °E. 18 lks.; now point covered by 62" Hemlock log.

30" Hemlock bears N64°E. 54 lks.; now 62" stump, scribes S12 visible, rest of upper face unexposed in log downhill, lower face unexposed.

See Books 159, 158, 157, 156, 155, 154, 153, 152, 151, 150, 149, 148, 147, 146, 145, 144, 143, 142, 141, 140, 139, 138, 137, 136, 135, 134, 133, 132, 131, 130, 129, 128, 127, 126, 125, 124, 123, 122, 121, 120, 119, 118, 117, 116, 115, 114, 113, 112, 111, 110, 109, 108, 107, 106, 105, 104, 103, 102, 101, 100, 99, 98, 97, 96, 95, 94, 93, 92, 91, 90, 89, 88, 87, 86, 85, 84, 83, 82, 81, 80, 79, 78, 77, 76, 75, 74, 73, 72, 71, 70, 69, 68, 67, 66, 65, 64, 63, 62, 61, 60, 59, 58, 57, 56, 55, 54, 53, 52, 51, 50, 49, 48, 47, 46, 45, 44, 43, 42, 41, 40, 39, 38, 37, 36, 35, 34, 33, 32, 31, 30, 29, 28, 27, 26, 25, 24, 23, 22, 21, 20, 19, 18, 17, 16, 15, 14, 13, 12, 11, 10, 9, 8, 7, 6, 5, 4, 3, 2, 1

RESTORED

Var. 21 $\frac{1}{2}$ °E.

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S, R9W, S12 S14 S13 1957 RS401," 33 inches in ground, in small mound of stone, and from which a:

23" Fir bears S76°E 73.9 ft.; scribed T1S R9W S13 BT RS401.


24" Fir bears N36°E 78.3 ft.; scribed T1S R9W S12 BT.

Oregon State Board of Forestry metal location poster on 10" Hemlock N52°E 3.7 ft.


Set 3" x 4" x 60" white painted cedar post 1.5 ft. NE.

Dated May 23, 1957

Restored by



Richard A. Morris



Present and witnessed by Robert Sturm
Craig Chambers