

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 5 and 8,
T.3N., R.6W., W.M., Tillamook County, Oregon.

ORIGINAL

24" x 18" x 18" stone (now in place with cross on top,
1/4 on N. face, and a 1 1/2" x 48" iron pipe on SE edge),
from which a:

- 4" Fir bears N74°E 105 lks.; now 38" stump,
portion of scribe visible, rest unexposed.
- 48" Fir bears S39°E 35 lks.; now 48" snag, scribes
1/4 S visible, rest unexposed.

RESTORED

Erected mound of stone around above pipe and south side
of 1/4 stone, from which a:

- 14" Hemlock bears S62°E 21.7 ft.; scribed 1/4 S8 BT.
- 12" Noble Fir bears N51°E 29.0 ft.; scribed 1/4 S5
BT RS401.

Oregon State Board of Forestry metal location poster on
12" Noble Fir BT.

Set 4" x 4" x 60" white painted cedar post 2.0' SW.

Dated May 23, 1957.

Restored by



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401

Presented and witnessed by Robert Sturm
Craig Chambers