

394

394

CHAINS

A

Rewitness of Corner of Sections 19, 20, 29 and 30, T. 2 S., R. 10 W., W.M.

Found evidence of all four B.T.'s as follows:

- 24" Hemlock North 60°E rotten windfall.
- 22" Hemlock North 22°W, still green with scribing visible.
- 20" Hemlocks both snags, The S.E. only a rotten stub.

Set 1" Iron Pipe with babbited 3" Cap stamped

T. 2 S.
Sec 19/20
30/29
R. 10 W.

in true original position, from which, I scribed for new Bearing Trees:

A 10" Hemlock bears N 3½°E, 14.3 ft. distant marked S20 B.T. 376#

A 40" Cedar bears S. 3½°E., 42.5 ft. distant marked S 29 B.T. 376#

In the presence of Jerry Gass, Sept. 24 and 27, 1956

REGISTERED
LAND SURVEYOR

Charles G. Collard
Registered Land Surveyor
Oregon No. 376

MAY 4, 1956
CHARLES G. COLLARD

Rewitness of Section Corner 1, 2 11 and 12, T.3 S., R 10 W., W.M.

Because of road construction which necessitated destruction of the Bearing Trees for Sections 1 and 2, I rewitnessed as follows:

A 21" Hemlock bears N.35°E, 54.3 ft. marked S1 B.T. # 376

A 17" Hemlock bears N. 1° 30'W, 52.9 ft. marked S2 B.T. #376

The Section 12 B.T. now a 16" Hemlock still bears S 3°E, 74.1 ft. and the 2" Iron Pipe remains in place though now is on the South edge of the relocated road.

REGISTERED
OREGON
LAND SURVEYOR

August 19, 1957
In the presence of Jerry Gass

Charles G. Collard
Registered Land Surveyor
Oregon No. 376

MAY 4, 1956
CHARLES G. COLLARD
376

Rewitness of 1/4 Section corner between Section 5, T. X S, R 10 W. and Section 32, T. Z S., R 10 W., W.M.

August 29, 1956

Found Bearing Trees scribed by County Surveyors Anderson and Gustrom in 1924 down at West edge of timber, the timber west of the corner having been logged, with the old corner stake up-rooted intact with the earth wad of the closest tree.

After estimating the position of the trees when they were standing, I set an iron pipe in the exact location called for in Anderson's notes. This coincided with the estimated original position of the uprooted stake. The iron pipe is 3/4" galvanized pipe, 20 " in the ground and 4" above, with 1½" babbited cap marked:

- from which I scribed new bearing trees:
- 12" Hemlock marked 1/4 B.T. # 376 bears S 76°E, 58.6 ft.
- 16" Hemlock marked 1/4 B.T. # 376 bears S 40°40' East, 80.2 ft. distant.

T. 1 S.
Sec 5
1/4
R. 10 W.
Sec 32

REGISTERED
OREGON
LAND SURVEYOR

Charles G. Collard
Registered Land Surveyor
Oregon # 376

MAY 4, 1956
CHARLES G. COLLARD
376

BOOK 2

394

394