

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 10 and 15,
Ts. 2N, Rge. 7W, W.M., Tillamook County, Oregon.

ORIGINAL

20"xl4"x5" stone (now missing) from which a:

25" Fir bears S56°E 32 lks.; now 28" stump, faces cut off
when logged.

28" Fir bears N72°W 34 lks.; now 34" stump, scribes BT
visible, rest cut off when logged.

RESTORED

Var. 21½°E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY ¼ S10 S15 1957 RS 401,"
28 Inches in ground, in mound of stone, and from which a:

43" Fir stump bears N8°W 21.0 ft.; scribed ¼ S10 BT RS 401.


31" Fir stump bears S73½°W 37.4 ft.; scribed ¼ S15 BT.

Oregon State Board of Forestry metal location poster on 43" Fir
stump BT.

Set 3"x4"x60" white painted Cedar post 1.5' SE.

Dated July 24, 1957.

Restored by



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401

Present and witnessed by Robert Sturm
Harold Russell