

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 13, 18, 19 and 24,
T. 2N, R. 7&8W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 20"x12"x9" (now in place and broken
3 chisel marks on N and S faces visible) from which a:

- 48" Hemlock bears N37°E 42 lks.; now 48" uproot, roots and root hole in place, face and scribes burnt off.
- 18" Hemlock bears S25°E 40 lks.; now missing.
- 10" Hemlock bears S44°W 78 lks.; now just roots remaining in place.
- 18" Hemlock bears N16°W 69 lks.; now 19" uproot, roots in place, bottom of burnt out face visible.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R8W R7W S13 S18 S24 S19 1957 RS 401," 33 inches in ground, broken original stone on N edge of pipe, in mound of stone, and from which a:

- 56" Fir stump bears S74°W 33.4 ft.; scribed T2N R8W S24 BT RS 401.
- 55" Fir stump bears S75°E 60.0 ft.; scribed T2N R7W S19 BT.
- 50" Fir stump bears N83°W 65.3 ft.; scribed T2N R8W S13 BT.
- 52" Fir stump bears N2°E 40.2 ft.; scribed T2N R7W S18 BT.

Set 4"x4"x60" white painted Cedar post 1.3' SE of pipe. Oregon State Board of Forestry metal location poster on 56" Fir stump BT.

Also poster on 4"x4"x60" white painted Cedar post 363.0 ft. S on S edge of road.

Dated August 1, 1957.

Restored by



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401

Present and witnessed by Robert Sturm and Harold Russell