

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 10 and 11,  
TLN, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 15" Hemlock bears N20W 5 lks.; now 30" stump, scribes BT visible, upper face unexposed.
- 12" Hemlock bears S50E 40 lks.; now 12" stub 3' high, face and scribes rotted off.

RESTORED

Var.  $21\frac{1}{2}^{\circ}$  E

Set  $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S10 S11 1959 RS401", 33 inches in ground, and from which a:

- 9" Hemlock bears S67 $\frac{1}{2}$ E 23.2 ft.; scribed 1/4 S11 BT RS401.
- 14" Hemlock bears S11 $\frac{1}{4}$ W 17.5 ft.; scribed 1/4 S10 BT.

Oregon State Board of Forestry metal location poster on 14" Hemlock BT.  
Set 4" x 4" x 52" white painted Cedar post 1.0' N.E. of pipe.

Dated December 31, 1959

Restored by



Present and witnessed by H. Russell  
R. Cop  
E. Nylund