

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 35 and 36,  
T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (found rotted Spruce limb with axed point in place) from which a:

96" Fir bears N72W 67 lks.; now 71" Fir snag face and scribes  
rotted off.

8" Hemlock bears N81E 55 lks.; now missing.

15" Lk. wide branch course SW bears North 7 chs.; now 24" creek  
S65W, in place.

Ridge top bears South 12 chs.; course NE by N & SW; now in place.

RESTORED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE  
BOARD OF FORESTRY 1/4 S35 S36 1959 RS401", 32 inches in ground, and  
from which a:

33" Spruce bears N26 $\frac{1}{2}$ E 19.0 ft.; scribed 1/4 S36 BT RS401.


30" Hemlock bears N15W 68.7 ft.; scribed 1/4 S35 BT.

Oregon State Board of Forestry metal location poster on 33" Spruce BT.

Set 4" x 4" x 60" white painted Cedar post 1.0' N.E. of pipe.

Dated December 31, 1959

Restored by



*Richard A. Morris*  
MAY 10, 1957  
Richard A. Morris  
401

Present and witnessed by H. Russell  
R. Cop  
E. Nylund  
D. Jones