

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 28, 29, 32 and 33, T1N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing, corner point is in slide area) from which a:

12" Hemlock bears N25W 59 lks.; now 18" broken off stub 3' high, broken off portion down hill with scribes T1N visible, rest burnt off.

56" Cedar bears N26E 38 lks.; now missing, point falls in slide area.

35" Cedar bears S71E 112 lks.; position covered by cat road debris.

4" Vine Maple bears S30W 28 lks.; now missing.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R7W S29 S28 S32 S33 1959 RS401", 33 inches in ground, and from which a:

48" Cedar stump bears N27 1/2 W 41.7 ft.; scribed T1N R7W S29 BT.

52" Fir stump bears N4E 38.6 ft.; scribed T1N R7W S28 BT.


7" Fir bears S37E 129.2 ft.; scribed T1N R7W S33 BT RS401.

Oregon State Board of Forestry metal location poster on 48" Cedar stump BT.

Set 4" x 4" x 50" white painted Cedar post 1.0' N.E. of pipe.

Dated December 31, 1959

Restored by



Richard A. Morris
MAY 13 1959
Richard A. Morris
401

Present and witnessed by M. Flippin