

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 2 and 11,  
T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing, found 1" iron pipe in place) from which a:

30" Hemlock bears S25E 17 lks.; now 30" stub 15' high, edges of rotted  
out face visible, no scribes remaining.

RESTORED

Set 4" x 4" x 60" white painted Cedar post 1.0' S.E. of above 1" iron  
pipe from which a:


17" Spruce bears S74W 23.8 ft.; scribed 1/4 S11 BT RS401.

13" Hemlock bears N86E 26.5 ft.; scribed 1/4 S2 BT.

Oregon State Board of Forestry metal location poster on 13" Hemlock BT.

Dated December 31, 1959

Restored by



*Richard A. Morris*  
MAY 10. 1937  
Richard A. Morris  
401

Present and witnessed by M. Flippin