

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 8, 9, 16 and 17,
T3S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

60" Fir for corner (now 86" snag, scribed S9 on N.E., R8W S16 on S.E., burnt
out face N.W., old face no scribes S.W.) from which a:

- 4" Barberry bears N62W 15 lks.; now missing.
- 4" Barberry bears N44E 16 lks.; now missing.
- 8" Alder bears S24E 107 lks.; now 26" Alder no face exposed.
- 4" Alder bears S58W 9 lks.; now missing.

RESTORED

Set 4" x 4" x 54" white painted Cedar post on N.W. side of corner tree from
which a:

- 10" Hemlock bears S62W 19.8 ft.; scribed T3S R8W S17 BT RS401.
- 17" Fir bears N61W 27.5 ft.; scribed T3S R8W S8 BT.
- 11" Hemlock bears S88 $\frac{1}{2}$ E 61.1 ft.; scribed T3S R8W S16 BT.
- 26" Fir bears N74E 64.6 ft.; scribed T3S R8W S9 BT.

Oregon State Board of Forestry metal location poster on 17" Fir BT.

Dated March 3, 1960

Restored by

REGISTERED
 OREGON
 LAND SURVEYOR

Richard A. Morris

Richard A. Morris
 401

Present and witnessed by R. Cop
 E. Nylund
 M. Flippen