

CHAINS

REESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 13, 18, 19 and 24,  
T1N, R9 and 10W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found) from which:

Moss Creek bears North 150 lks.; now in place.  
Moss Creek bears West 500 lks.; now in place.

Original line blaze in 60" Cedar stump bears N1°39'08"W 409.6'  
Corner set in edge of creek bottom; in place.

REESTABLISHED

Var. 21½E

At a point on a line projected over the above original line blaze from  
the 1/4 common to Secs. 13 and 18 1.50 chs. S1°34'08"E of Moss Creek  
set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON  
STATE BOARD OF FORESTRY T1N R10W R9W S13 S18 S24 S19 1959 RS401", 35  
inches in ground, in mound of stone, and from which a:

8" Hemlock bears S37E 57.2 ft.; scribed T1N R9W S19 BT.  
11" Spruce bears N76½E 43.7 ft.; scribed T1N R9W S18 BT.  
36" Spruce bears N10W 23.0 ft.; scribed T1N R10W S13 BT RS401.  
35" Spruce bears S58W 34.7 ft.; scribed T1N R10W S24 BT.

Oregon State Board of Forestry metal location poster on 36" Spruce BT.  
Set 4" x 4" x 56" white painted Cedar post 1.5' N.W. of Corner

Dated December 30, 1959

Reestablished by



*Richard A. Morris*  
MAY 19, 1957  
Richard A. Morris  
401

Present and witnessed by A. Gibson