

CHAINS

REESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 23 and 26, T1N, R10W, W.M., Tillamook County, Oregon.

REESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S23 S24 1959 RS401", 30 inches in ground, and from which a:

- 12" Hemlock bears S17 1/4 E 26.1 ft.; scribed 1/4 S26 BT RS401.
- 9" Hemlock bears N38 1/2 W 28.9 ft.; scribed 1/4 S23 BT.

Oregon State Board of Forestry metal location poster on 12" Hemlock S38E 4.2 ft.

Set 4" x 4" x 60" white painted Cedar post 1.0' NW of pipe.

ESTABLISHED CORNER FOR OREGON STATE BOARD OF FORESTRY
Center One Quarter corner for Section 26, T1N, R10W,
W.M., Tillamook County, Oregon.

~~REESTABLISHED~~

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 0 1/4 S26 1959 RS401", 26 inches in ground, in mound of stone, and from which a:

- 14" Spruce bears S17 1/2 W 6.9 ft.; scribed 0 1/4 S26 BT RS401.
- 23" Spruce bears N22 1/2 E 9.6 ft.; scribed 0 1/4 S26 BT.

Oregon State Board of Forestry metal location poster on 14" Spruce BT.

Set 4" x 4" x 56" white painted Cedar post 1' SE of pipe.

Corner is on SE edge of 60" Spruce stub 10' high.

Dated December 31, 1959

Reestablished by



Present and witnessed by H. Russell
R. Cop
E. Nylund
D. Jones