

County Surveyor's Record, Tillamook County, Oregon

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 13 and 14,
T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

24" Hemlock bears N34E 33 lks.; now missing.

58" Spruce bears S88W 24 lks.; now rotted stub 2' high, face and scribes
rotted away.

NOTE: After retracing the county survey by W. E. Anderson for Fred Wyss
March 1935, and the county survey by U. G. Jackson May 1, 1914, and
having both surveys agree within 15 ft. of each other for the 1/4
corner common to Sections 13 and 14 and there being the remains of
only one large Spruce tree in this area, I accept this Spruce as
the above original bearing tree.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S14 S13 1959 RS401", 32 inches in ground, and from
which a:

31" Hemlock bears N18E 51.7 ft.; scribed 1/4 S13 BT.

26" Hemlock bears N31W 68.1 ft.; scribed 1/4 S14 BT RS401.

Oregon State Board of Forestry metal location poster on 26" Hemlock BT.

Set 4" x 4" x 60" white painted Cedar post 1.0' N.W. of pipe.

Dated December 31, 1959

Restored by



Richard A. Morris
MAY 10 1957
Richard A. Morris
401

Present and witnessed by H. Russell
R. Cop
E. Nylund
N. J. Widenoja