

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 10 and 15,  
T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

40" Hemlock bears S20E 17 lks.; now 48" stub 2' high, face and scribes  
rotted away.

36" Hemlock bears N10W 33 lks.; now 37" uproot, back cast of scribes BT  
visible, both faces rotted away, roots and root hole in place.

RESTORED

Var. 21½E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE  
BOARD OF FORESTRY 1/4 S10 S15 1960 RS401", 33 inches in ground, and from  
which a:


12" Hemlock bears N55½E 16.0 ft.; scribed 1/4 S10 BT.

16" Hemlock bears S30½E 14.4 ft.; scribed 1/4 S15 BT RS401.


Oregon State Board of Forestry metal location poster on 16" Hemlock BT.  
Set 4" x 4" x 52" white painted Cedar post 1.0' N.E. of pipe.

Dated December 2, 1960

Restored by \_\_\_\_\_ under my direction.  
~~R. Morris, Transitman~~



*Richard A. Morris*



Present and witnessed by E. Nylund

9/27