

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 7 and 12,
T3S, R8 & 9W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 18" x 12" x 9" (found possible 1/4 stone 6" x 6" x 8" with possible
chisel marks on it and with 3/4" x 24" iron pipe alongside) from
which a:

12" Alder bears S74W 101 lks.; now 24" stub 4' high, rotted outline
of face visible.

10" Alder bears S38E 42 lks.; now missing.

Brook 4 lks. bears North 15 lks.; now in place, runs S.W.

Old line blazes to the North and South of this corner point.
Above pipe set by M. Whitmore U.S.F.S.

RESTORED

Placed mound of stone around above 3/4" x 24" I.P. from which a:


30" Fir bears N80 1/2 E 53.0 ft.; scribed 1/4 S7 BT.

13" Hemlock bears S71W 55.0 ft.; scribed 1/4 S12 BT RS401.


Oregon State Board of Forestry metal location poster on 13" Hemlock BT.
Set 4" x 4" x 54" white painted Cedar post 1.0' N.E. of pipe.

Dated November 17, 1960

Restored by



Richard A. Morris



Present and witnessed by R. Cop
G. Nylund
E. Hunt
D. Jordan
L. Wilkens

447