

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 2, 3, 34 and 35,
T1 & 2N, R10W, W.M.; Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 4" Alder bears N30W 7 lks.; now just rotted roots remaining in place.
- 7" Alder bears N78E 4 lks.; now missing.
- 6" Alder bears S30W 3 lks.; now missing.

RESTORED by County Surveyor, 1888

Vinemapple post (now missing) from which a:

- 14" Alder (orig.) bears N30W 7 lks.; see above.
- 16" Alder bears N87E 4 lks.; now down, badly rotted, roots in place.
- 16" Alder bears N9½E 24 lks.; now 25", bark scribes CS T2N BT visible.
- 18" Alder bears S3W 3 lks.; now 24", bark scribes CS T1N R10W BT visible.

RESTORED

Var. 21½E


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R10W S34 S35 S3 S2 T1N 1960 RS401", 28 inches in ground, and from which a:

- 78" Spruce bears N57W 35.5 ft.; scribed T2N R10W S34 BT RS401.
- 26" Alder bears S35E 56.8 ft.; scribed in bark, T1N R10W S2 BT.


Oregon State Board of Forestry metal location poster on 78" Spruce BT.
Set 4" x 4" x 52" white painted Cedar post 0.7' West of pipe.

Dated October 17, 1960

Restored by



Richard A. Morris



Present and witnessed by Harold Russell
George Nylund