

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 7, 12, 13 and 18, T3S, R9 & 10W, W.M., Tillamook County, Oregon.

ORIGINAL

10" Fir corner tree (now 20" stub 2' high, scribes R10W visible on W. side, S12 on NW side, R9W on E, rest unexposed) from which a:

10" Hemlock bears S77W 8 lks.; now 13" uproot, edges of rotted out face visible, roots in place.

9" Hemlock bears S10E 9 lks.; now 19" uproot, edges of rotted out face visible, roots in place.

10" Fir bears N14W 23 lks.; now 14" stub 4' high, portion of scribes visible.

3 1/2" Fir bears N32E 100 lks.; now missing.

RESTORED

Var. 21 1/2 E

Drove 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3S R10W R9W S12 S7 S13 S18 1960 RS401", 24 inches into corner stub, and from which a:

16" Hemlock bears N51E 22.1 ft.; scribed T3S R9W S7 BT.

8" Hemlock bears S45 1/2 E 40.4 ft.; scribed T3S R9W S18 BT.


20" Hemlock bears S75W 11.7 ft.; scribed T3S R10W S13 BT.

18" Hemlock bears N34 1/2 W 25.7 ft.; scribed T3S R10W S12 BT RS401.


Oregon State Board of Forestry metal location poster on 20" Hemlock BT.  
Set 4" x 4" x 54" white painted Cedar post 2.6' N.W. of pipe.

Dated December 2, 1960

Restored by



*Richard A. Morris*



Present and witnessed by H. Russell  
R. Cop  
G. Nylund

458