

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 9, 10, 15 and 16, T1N, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

- 14" Hemlock bears N39W 43 lks.; now missing.
- Spring branch, course East, bears South 170 lks.; now in place.
- Spring branch, course S45E, bears West 250 lks.; now in place.
- Spring branch, course S15W, bears East 950 lks.; now in place.
- Spring branch, course South, bears East 640 lks.; now in place.

RESTORED

Var. 21½E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1N R10W S9 S10 S16 S15 1960 RS401", 33 inches in ground, in mound of stone, and from which a:

- 12" Hemlock bears S43W 28.4 ft.; scribed T1N R10W S16 BT.
- 16" Hemlock bears S19E 11.5 ft.; scribed T1N R10W S15 BT.
- 11" Spruce bears N73W 25.0 ft.; scribed T1N R10W S9 BT.
- 25" Hemlock bears N2E 21.5 ft.; scribed T1N R10W S10 BT RS 401.


Oregon State Board of Forestry metal location poster on 16" Hemlock BT.  
Set 4" x 4" x 52" white painted Cedar post 1.0' N.W. of pipe.

Dated October 24, 1960

Restored by



*Richard A. Morris*



Present and witnessed by Harold Russell  
George Nylund