

CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY
(See official plat)

One Quarter corner common to Sections 12 and 13, T3S,
R10W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S12 S13 1961 RS401", 24 inches in ground, and from
which a:

7" Hemlock bears S69W 16.9 ft.; scribed 1/4 S13 BT RS401.

8" Hemlock bears N12W 30.9 ft.; scribed 1/4 S12 BT.

Set 4" x 4" x 52" white painted Cedar post 1.0 ft. SE of corner pipe.
Oregon State Board of Forestry metal location poster on 7" Hemlock BT.

Present and witnessed by H. Russell, R. Cop, E. Nylund

Reestablished by Richard Morris

One Quarter corner common to Sections 11 and 12, T3S,
R10W, W.M., Tillamook County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S11 S12 1961 RS401", 34 inches in ground, and
from which a:

22" Hemlock bears S43E 61.3 ft.; scribed 1/4 S12 BT RS401.

6" Hemlock bears N46 1/2 W 14.1 ft.; scribed 1/4 S11 BT.


Oregon State Board of Forestry metal location poster on 22" Hemlock BT.

Set 4" x 4" x 52" white painted Cedar post 1.0' S.E. of pipe.

Reestablished by Harold J. Russell under my direction.
Harold Russell, Eng. Tech. I

Present and witnessed by E. Nylund

Dated February 16, 1961



Richard A. Morris

