

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner common to Sections 1 and 12,
T3S, R10W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 10" Spruce bears S24E 13 lks.; now missing.
- 8" Spruce bears N34W 39 lks.; now 15" stub 20' high, scribes B and part of T visible. Rest of face unexposed.

RESTORATION by County Surveyor 1888

Cedar stake (now missing)

RESTORED

Var. 21 $\frac{1}{2}$ °E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S1 S12 1961 RS401", 32" in ground, and from which a:

- 39" Hemlock bears S17 3/4 W 48.5 ft.; scribed 1/4 S12 BT RS401.
- 27" Spruce bears N79E 26.1 ft.; scribed 1/4 S1 BT.


Corner sets one foot South of 50" double Spruce tree.

Oregon State Board of Forestry metal location poster on 27" Spruce BT.
Set 4" x 4" x 52" white painted Cedar post 1.0' SW of pipe.

Dated February 14, 1961

Restored by Harold Russell under my direction.
Harold Russell, Engineering Tech. I

Present and witnessed by R. Cop
E. Nylund



Richard A. Morris
MAY 10. 1957
Richard A. Morris
401