

CHAINS

RE-ESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY
(See official plat)

One Quarter corner common to Sections 3 and 4, T1N,
R10W, W.M., Tillamook County, Oregon.

No evidence of original corner found.

RE-ESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S4 S3 1961 RS401", 34 inches in ground, in mound
of rock, and from which a:

- 22" Hemlock bears S44 1/2 W 61.8 ft.; scribed 1/4 S4 BT RS401.
- 12" Hemlock bears N36 1/2 E 42.7 ft.; scribed 1/4 S3 BT

Set 4" x 4" x 52" white painted Cedar post 1.0 ft. SE of corner pipe.
Oregon State Board of Forestry metal location poster on 60" Hemlock stump
N14 1/2 E 4.0.
Corner sets 22 feet East of Publishers Access Road, course N & S.

* * * * *

One Quarter corner common to Sections 33 and 4, T1
and 2N, R10W, W.M., Tillamook County, Oregon.

No evidence of original corner found.

RE-ESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S33 S4 1961 RS401", 33 inches in ground, and from
which a:

- 28" Hemlock bears N87 1/2 E 7.9 ft.; scribed 1/4 S33 BT RS401.
- 13" Hemlock bears S43 1/2 W 12.9 ft.; scribed 1/4 S4 BT.

Set 4" x 4" x 52" white painted Cedar post 1.0 ft. SE of corner pipe.
Oregon State Board of Forestry metal location poster on 28" Hemlock BT.

Dated February 27, 1961

Re-established by

Present and witnessed by H. Russell
R. Cop
E. Nylund



Richard A. Morris
MAY 10, 1957
Richard A. Morris
401

490