

CHAINS

REESTABLISHED CORNERS FOR OREGON STATE BOARD OF FORESTRY
(See official plat)

One Quarter corner common to Sections 7 and 12, T1N,
R 9 and 10W, W.M., Tillamook County, Oregon.

No evidence of original corner found.

RE-ESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY 1/4 S12 S7 1961 RS401", 33 inches in ground, and from
which a:

- 56" Spruce bears S30 1/2 E 24.9 ft.; scribed 1/4 S 7 BT RS401.
- 24" Hemlock bears S33 W 49.4 ft.; scribed 1/4 S12 BT.

Set 4" x 4" x 52" white painted Cedar post 1.0 ft. S.E. of corner pipe.
Oregon State Board of Forestry metal location poster on 36" Cedar N3E 18.3'.

Section corner common to Sections 7, 12, 13 and 18,
T1N, R9 & 10W, W.M., Tillamook County, Oregon.

No evidence of original corner found.

RE-ESTABLISHED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE
BOARD OF FORESTRY T1N R10W R9W S12 S7 S13 S18 1961 RS401", 33 inches in
ground, and from which a:

- 36" Hemlock bears S8E 31.1 ft.; scribed T1N R9W S18 BT.
- 11" Hemlock bears S42W 53.2 ft.; scribed T1N R10W S13 BT.
- 6" Hemlock bears N11W 25.4 ft.; scribed T1N R10W S12 BT.
- 22" Hemlock bears N53 1/2 E 23.9 ft.; scribed T1N R9W S7 BT RS401.

Oregon State Board of Forestry metal location poster on 19" Cedar N80E 19.4'.
Scribes S7 BT on S.W. side of above 19" Cedar by Longview Fibre Co.
Scribes S18 BT on NW side of above 36" Hemlock by Longview Fibre Co.
3/4" stainless steel pipe S15 1/2 W 28.0, set by Longview Fibre Co.

Dated February 27, 1961

Re-established by

Present and witnessed by H. Russell
R. Cop
G. Nylund



Richard A. Morris

