

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Township corner common to Sections 31 and 6 (West end) T1 & 2S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing, found remains of iron pipe ~~and XXXXX~~ and 1" iron bolt with nut in place) from which a:

- 12" Spruce bears N46E 40 lks.; rotted and burnt root stubs remaining.
- 36" Spruce bears S54E 34 lks.; now 40" stump, scribes T2S R8W S6 BT remaining.
- 36" Hemlock bears N72W 10 lks.; burnt and rotted face remaining.
- 30" Spruce bears S37W 35 lks.; burnt and rotted face, scribes visible on upper and lower faces.

NOTE: The latter two BT's were not mentioned in notes but were definitely original.

RESTORATION by John H. Forrest and James G. Reid 1950

Set iron pipe 5 ft. long 2 ft. in ground (rusted pieces remaining) from which a:

- 3" Spruce bears N79E 35.0 ft.; now 10" Hemlock in place, scribes visible.

RESTORED

Var. 20 1/2



Set 4 x 4 x 72" white painted Cedar post 1.5 ft. SE of bolt corner from which a:

- 9" Fir bears N69E 12.6 ft.; scribed T1S R8W S31 BT.
- 13" Alder bears S36 1/2 E 6.0 ft.; bark scribed T2S R8W S6 BT.
- 7" Hemlock bears S71W 10.5 ft.; scribed RS359.

Oregon State Board of Forestry metal location poster on 13" Alder BT.

Dated May 11, 1961

Restored by



Present and witnessed by C. Skog
D. Jordan
L. Wilkins