

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Var. $21\frac{1}{2}^{\circ}$ E

Closing Section (East Side) corner common to Sections 1 and 12, T.3N, R.9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) by H. Meldrum from which a:

- 10" Hem. bears $N74^{\circ}W$ 17 lks.; now 28" downed snag, face rotted away, back cast of scribes BT remaining.
- 10" Hem. bears $S48^{\circ}W$ 58 lks.; now missing.
- 10" Hem. bears $S52^{\circ}E$ 45 lks.; now missing.

RESTORED


Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R9W CC S1 S12 S6 1963 RS 605", 32 inches in ground, in mound of rock and from which a:

- 7" Hem. bears $S70^{\circ}W$ 4.0 ft.; scribed T3N R9W S12 CC BT.
- 30" Hem. bears $N38^{\circ}W$ 19.6 ft.; scribed T3N R9W S1 CC BT RS 605.
- 20" Hem. bears $N26^{\circ}E$ 16.0 ft.; scribed T3N R8W S1 S12 CC BT.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SW of corner pipe. Oregon State Forestry Department metal location poster on 7" Hem. BT. Section corner 1 and 12, T3N, R9W, destroyed by Meldrum bears South approximately 451.4 ft. Restored but not recorded by Paul Thompson.

Dated September 12, 1963.

Restored by



Present and witnessed by Larry Hayes