

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One quarter corner common to Sections 11 and 14, T3S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

5" Fir bears N41E 16 lks.; now 5 1/2" stub 2' high scribes BT on lower face, upper face rotted away.

9" Fir bears S48° 45' W 31 lks.; now 23", face grown over.

RESTORED

Var. 21 1/2 E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S11 S14 1964 RS401", 32 inches in ground, and from which a:

24" Fir bears N37E 19.6 ft.; scribed 1/4 S11 BT RS401.

Orig. Fir BT bears S48°45'W 20.5 ft.; scribed BT on new face.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SW of corner pipe. Oregon State Forestry Department metal location poster on 25" Fir N74 1/2 E 7.4 ft.

Dated May 4, 1964.

Restored by *Harold J. Russell* under my direction.
Harold J. Russell, Transitman

Present and witnessed by A. Duncan
C. Curl

