

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One quarter corner common to Sections 10 and 15, T2S, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 56" Hem. bears N61°E 20 lks.; roots in place.
- 8" Hem. bears S60°W 37 lks.; now 52" Hem. stump, backcast of lower face visible, inside of stump rotted out, along butt from same stump bears N75°W approximately 35 ft. with scribed  $\frac{1}{4}$ S visible inside.

RESTORATION by County Sureveyor, 1890 (BOOK 10 PAGE 77)

Post (now missing) from which a:

- 6" Hem. bears N33°W 89lks.; now 39" Hem. stump, scribes C S visible, rest of face unexposed.
- 10" Hem. bears S2°E 56 lks.; now missing, cat road through point.

RESTORED

Var. 21 $\frac{1}{2}$ E

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY  $\frac{1}{4}$  S10 S15 1964 RS 401", and from which a:

- 11" Spruce bears N74°W 33.7 ft.; scribed  $\frac{1}{4}$  S10 BT RS 401.
- 12" Hem. bears S2 $\frac{1}{2}$ °E 179.6 ft.; scribed  $\frac{1}{4}$  S 15 BT.

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. SE of corner pipe. ~~Oregon State Forestry Department metal location poster on~~

Dated February 2, 1965

Restored by Harold J. Russell under my direction.  
Harold J. Russell, Transitman

Present and witnessed by A. Duncan

