

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 3, 4, 33 and 34, T3 and 4N, R9W, W.M., Tillamook and Clatsop Counties, Oregon.

33 134 4 N 9
4 3 3 N 9

ORIGINAL

Post (missing) from which a:

- 90" Spruce bears N11 1/2 E 74 lks.; now 84" rotted stump, no face or scribes visible.
- 28" Hem. bears S28 1/2 E 42 lks.; now 28" shell of rotted stump, no scribes or face visible.
- 18" Hem. bears S42 3/4 W 38 lks.; missing.
- 18" Hem. bears N21 1/2 W 55 1/2 lks.; roots remaining in ground.
- 10 lk. creek course East, North 2.00 chs.; in place.
- 3 lk. creek course SE, North 5.00 chs.; in place.
- 2 lk. creek course SE, North 6.00 chs.; in place.

RESTORED

Var. 22° 15'E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T4N R9W S33 S34 S4 S3 T3N 1964 RS 401", 32 inches in ground, and from which a:

- 11" D. Fir bears S80E 52.0 ft.; scribed T3N R9W S3 BT.
- 7" Hem. bears N62E 40.3 ft.; scribed T4N R9W S34 BT.
- 10" Hem. bears S32W 39.9 ft.; scribed T3N R9W S4 BT.
- 18" Hem. bears N2W 57.4 ft.; scribed T4N R9W S33 BT RS 401.

Set 4" x 4" x 54" white painted Cedar post 1.0 ft. SW of corner pipe. Oregon State Forestry Department metal location poster on 6" Alder S60W 10.3 ft.

Dated December 31, 1964.

Restored by Robert Ross under my direction.
Robert Ross, Transitman

Present and witnessed by R. Martin
J. Martin
J. Gunderson



Richard A. Morris
MAY 10 1957
Richard A. Morris
461