

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

Section corner common to Sections 4, 5, 8 and 9, T3N, R9W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (now missing) from which a:

- 6" Hem. bears S30°E 67 lks.; now missing, roots in place.
- 10" Hem. bears S45°W 57 lks.; now 42" stub 6 ft. high, scribe B on lower face found inside, upper face rotted away.
- 15" Hem. bears N5°E 43 lks.; now missing.
- 18" Hem. bears N30°W 86 lks.; now missing.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R9W S4 S5 S8 S9 1965 RS 401", 33 inches in ground, and from which a:

- 14" Hem. bears N9 3/4°W 5.4 ft.; scribed T3N R9W S5 BT RS401.
- 13" Hem. bears N68°E 20.9 ft.; scribed T3N R9W S4 BT.
- 14" Hem. bears S6 1/2°E 9.5 ft.; scribed T3N R9W S9 BT.
- 8" Hem. bears S83°W 12.3 ft.; scribed T3N R9W S8 BT.

Set 4" x 4" x 60" white painted Cedar post 0.8 ft. NE of corner pipe. Oregon State Forestry Department metal location poster on 14" Hem. BT. N9 3/4°W.

Dated June 8, 1965

Restored by Harold J. Russell under my direction.
Harold J. Russell, Transitman

Present and witnessed by A. Duncan
C. Curl



Richard A. Morris
MAY 10, 1937
Richard A. Morris
401