

CHAINS

RESTORED CORNER FOR STATE OF OREGON-DEPARTMENT OF FORESTRY

One - Quarter corner common to Sections 3 and 34, T3&4N, R9W, W.M., Tillamook and Clatsop Counties, Oregon.

ORIGINAL

Post (now missing) from which a:

- 44" Cedar bears S79°30'W 26 lks.; now 44" Cedar windfall, roots in place.
- 30" Hem. bears N59E 21 lks.; now missing, creek in place.
- Crossing of 8 ft. creek, Cs. N30E, bears West 55.0 ft.
- Crossing of same creek, Cs. S30E, bears East 15.0 ft.

RESTORATION by Paul L. Thompson (not recorded)

(Found 3"x3"x50" cedar post scribed 1/4 S 34 on north side) from which a:

- 23" Alder bears N50°W 16.3 ft.; bark scribed 1/4 S
- 23" leaning double Alder bears S45°E 5.8 ft.; bark scribed 1/4 S.

RESTORED

Var. 21 1/2°E

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S34 S3 1965 RS 401", 34 inches in ground, in mound of rock, and from which a:


- 7" Hem. bears S11°W 37.0 ft.; scribed 1/4 S3 BT.
- 20" Spruce bears N86 1/2°W 67.6 ft.; scribed 1/4 S34 BT RS 401.

Set 4" x 4" x 60" white painted Cedar post 1.5 ft. NE of corner pipe. Oregon State Forestry Department metal location poster on 23" Alder N50°W 16.3 ft.

Dated June 8, 1965

Restored by Allan E. Duncan under my direction.
Allan E. Duncan, Eng. Tech.

Present and witnessed by C. Curl



Richard A. Morris

