

CHAINS

T5S R9W

EVALUATION AND RESTORATION OF LAND SECTION CORNERS

1/4 Corner common to Secs 27-28, W.M., Tillamook County, Oregon.

Original monument: Post in mound of earth made by falling of a tree.

Found 3/4" iron pipe 18" above ground in good condition in a mound of earth.

Found 30" fir, N.61° 30", E., 19½ ft. with healed witness scar

Found 36" fir, North, 6½ ft. with healed witness scar. *CHOPPED OPEN FOUND MKS. C.S.*

I have no record on hand as to who may have witnessed these two trees. This information may be either in the Tillamook or Yamhill County engineer's office.

By Leonard Whitmore, Tillamook County Dep. Surveyor. 3-20=65

Witnessed by: M. Whitmore  
D. Whitmore

See Notes for  
Sec 27/28 559  
Vacation Toll Road  
JLC

Also  
See Book 1, P. 91