

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 5 and 8, Township  
3 North, Range 10 West, W. M., Tillamook County, Oregon.

CHAINS

ORIGINAL

Post, now missing, found 8" x 4' tall Hemlock stub (scribe 1 remaining on North side) from which a:

20" Hemlock bears N66W 24 lks.; now 18", 4' high badly rotted stub, face and scribes rotted away.

7" Hemlock bears S73W 18.5 lks.; now 26", portion of the scribe 1 on partially exposed face.

RESTORED

VAR 21½ E

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY ¼ S5 S8 1966 RS 707" 20 inches in ground, beside corner stub, with center of cap over center of the stub, in mound of rock, and from which a:

12" Hemlock bears S20E 18.3 ft.; scribed ¼ S8 BT.

21" Hemlock bears N37E 10.2 ft.; scribed ¼ S5 BT.  
RS 707.

26" Hemlock bears S73W 12.2 ft.; scribed BT.  
(Original)

Set 4" x 4" x 60" white painted Cedar post 1.0 ft. NE of corner pipe. Oregon State Forestry Department metal location poster on 17" Hemlock N17W 3.2 ft.

Dated March 11, 1966

REGISTERED  
OREGON  
LAND SURVEYOR

Restored by

*Harold J. Russell*

JULY 9, 1965  
HAROLD J. RUSSELL  
707

Present and witnessed by C. Curl