

County Surveyor's Record, Tillamook County, Oregon

REMONUMENTATION OF CORNERS

T. 4 S., R. 7 W., W.M.

1/4 section corner between Sections 13 and 14

Found: Original stone marked 1/4 on West face. Stone is crumbly and cracked.

Maple 18", N 23° E, 28.0 feet with visible scribe on partially healed face. (BTS 13)

Scribed: Fir 23", S 06° W, 81.0 feet (1/4 S14 BT)

Set: 3/4" x 36" Galv. I.P., deposited stone alongside.

Corner for Sections 11, 12, 13, and 14

Found: Original stone with notch on East edge still visible.

Scribed: Fir 29", S 75° W, 32 feet (T. 4 S., R. 7 W., Sec. 14 BT)
Fir 32", N 21° W, 20.5 feet (T. 4 S., R. 7 W., Sec. 11 BT)
Fir 12", N 44° E, 19.0 feet (T. 4 S., R. 7 W., Sec. 12 BT)
Fir 22", S 78° E, 28.5 feet (T. 4 S., R. 7 W., Sec. 13 BT)

Set: 3/4" x 36" Galv. I.P., deposited stone alongside.



UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

14.5a
9182

District Office
3550 Liberty Road, S.
P.O. Box 3227
Salem, Oregon 97302

Rec'd 9/30/66

Tillamook County Surveyor
Tillamook County Courthouse
Tillamook, Oregon

Dear Sir:

Enclosed please find information on remonumentation of corners in

T. 4 S., R. 7 W., W.M.

Sincerely yours,

Leo J. Martin
Leo J. Martin