

Dependent Resurvey of a Portion of the W. Bdy. of T. 1 S., R. 9 W.

Chains

Timber, spruce, hemlock, fir, cedar, maple, and alder; undergrowth, salmonberry, devil's-club, huckleberry, thimbleberry, and reproduction.

N. 0° 06' E., along the W. bdy. of Section 18.

Descend 84 ft. over NW. slope, through heavy timber and dense undergrowth.

2.33 Branch, 6 lks. wide, course W.; ascend 83 ft. over steep rocky S. slope.

3.30 Top of bluff, edge bears E. and W.; ascend 150 ft. over gradual SW. slope.

11.45 Spur, slopes W.; descend 364 ft. over broken NW. slope, changing to N. slope.

21.54 Branch, 1 lk. wide, course NW.; ascend 30 ft. along W. slope.

24.60 Top of ascent, slopes W.; descend 135 ft. over NW. slope, changing to N. slope.

28.72 Creek, 1 lk. wide, course NW.; ascend 12 ft. along W. slope.

30.20 The corner of Sections 13 and 24 only, on the E. bdy. of T. 1 S., R. 9 W., recorded and monumented by the Oregon State Board of Forestry with an iron post, 1½ ins. diam., protruding 4 ins. above ground, firmly set, with 3 in. bronze cap mkd.

Oregon State Board of Forestry

T 1 S	T 1 S
S 13	R 9 W
S 24	S 18
R 9 W	
1955	
RE 2311	

from which the remaining original bearing tree:

The stump hole of an uprooted cedar, 30 ins. diam., bears S. 89° W., 59 lks. dist., with illegible scribe marks visible on opened blaze of tree trunk which has slid downhill into creek. (Record calls for a hemlock).

A tree marked by the County Surveyor in 1932:

A fir, partially dead, 60 ins. diam., bears S. 9½° E., 69 lks. dist., with scribe marks BT 50 on opened blaze.

A tree marked by the Oregon State Board of Forestry in 1955:

A hemlock, 10 ins. diam., bears N. 38° W., 45 lks. dist., with scribe marks T1S R9W S13 RE2311 BT visible on partially healed blaze.

Add marks BLM 1958 to the bronze cap, and mark a new bearing tree:

A hemlock, 10 ins. diam., bears S. 62° W., 58 lks. dist., mkd. T1S R9W S24 BT.

N. 2° 15' E., beginning new measurement.

Ascend 2 ft. along W. slope.