

Dependant Resurvey of a Portion of the W. Bdy. of T. 1 S., R. 8 W.

Chains

T. 1 S., R. 9 W.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

N 1/16 |
S 13 |
1938

from which

A hemlock, 10 ins. diam., bears S. $43\frac{1}{2}^{\circ}$ W., $12\frac{1}{2}$ lks. dist., bark scribed N 1/16 S13 BT.

A hemlock, 22 ins. diam., bears N. 62° W., 26 lks. dist., mkd. N 1/16 S13 BT.

Descend 20 ft. over NW. slope.

13.50 Branch, 2 lks. wide, course SW. curving to S.; ascend 145 ft. over steep rocky S. slope.

14.70 Spur, slopes SW.; ascend 486 ft. along W. slope, changing to SW. slope.

27.00 Head of ravine, drains S. 10° W.; ascend 60 ft. over S. slope.

28.37 Point for the corner of Sections 12 and 13 only, on the E. bdy. of T. 1 S., R. 9 W., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 1 S | T 1 S
S 12 | R 8 W
S 13 | S 7
R 9 W |
1938

from which

A hemlock, 11 ins. diam., bears S. 40° W., 33 lks. dist., mkd. T1S R9W S13 BT.

A hemlock, 48 ins. diam., bears N. 37° W., 22 lks. dist., mkd. T1S R9W S12 BT.

Ascend 242 ft. over steep rocky SE. slope.

33.00 Ridge, bears N. 70° E. and S. 70° W.; descend 31 ft. over NW. slope.

37.33 The $\frac{1}{4}$ sec. cor. of Section 7 only, determined at record bearing and distance from the original bearing trees, recorded and remonumented by the Oregon State Board of Forestry with an iron post, $1\frac{1}{2}$ ins. diam., protruding 6 ins. above ground, firmly set, with 3 in. bronze cap mkd.

Oregon State Board of Forestry

|
 $\frac{1}{4}$ S 7
1955
RE 2311

from which the original bearing trees:

A rotted hemlock stub, 10 ins. diam., bears N. 62° E., 38 lks. dist., with no marks remaining.