

Dependent Resurvey of Portion of Subdivisional Lines of T. 1 S., R. 9 W.

| Chains | Land, mountainous. Soil, rocky clay and loam. Timber, hemlock, spruce, fir, alder, and cascara; undergrowth, salmonberry, thimbleberry, vine maple, salal, and reproduction. |
|--------|--|
| | From the cor. of secs. 10 and 15, only, on the W. bdy. of sec. 11. S. 89° 45' W., bet. secs. 10 and 15. Ascend 140 ft. over E. slope, through heavy timber and light undergrowth. |
| 7.20 | Main ridge, dividing Kilchis River and Wilson River drainage, bears N. 30° E. and S. 30° W.; desc. 23 ft. over NW. slope. |
| 9.66 | Ravine, drains N. 20° W.; asc. 177 ft. over NE. slope. |
| 18.60 | Spur, slopes N. 30° E.; desc. 18 ft. over NW. slope. |
| 19.94 | Point for the E 1/16 sec. cor. of secs. 10 and 15. Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> $\begin{array}{r} \text{E } 1/16 \quad \frac{\text{S } 10}{\text{S } 15} \\ 1958 \end{array}$ </div> from which A hemlock, 27 ins. diam., bears N. 10° W., 40½ lks. dist., mkd. E 1/16 S10 BT. A hemlock, 27 ins. diam., bears S. 47° E., 20½ lks. dist., mkd. E 1/16 S15 BT. The corner falls at head of ravine draining N. |
| 27.10 | Spur ridge, bears N. and S.; desc. 77 ft. along N. slope, changing to NW. slope. |
| 34.60 | Ravine, drains N. 20° E.; asc. 140 ft. over NE. slope. |
| 39.88 | Point for the ¼ sec. cor. of secs. 10 and 15, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, in a mound of stone, 2½ ft. base, to top, with brass cap mkd. <div style="text-align: center;"> $\begin{array}{r} \text{T } 1 \text{ S } \text{ R } 9 \text{ W} \\ \frac{1}{4} \quad \frac{\text{S } 10}{\text{S } 15} \\ 1958 \end{array}$ </div> from which A fir, 22 ins. diam., bears N. 67° W., 8½ lks. dist., mkd. ¼ S10 BT. A fir, 12 ins. diam., bears S. 58° E., 37 lks. dist., mkd. ¼ S15 BT. The corner falls on main ridge dividing Kilchis River and Wilson River drainage, bears S. 70° E. and W. Ascend 9 ft. along ridge. |
| 47.80 | Leave ridge, bears N. 50° W. and E.; desc. 512 ft. along steep, rocky broken S. slope, through scattering timber and dense undergrowth. |