

CHAINS

Page 15.

The alder post is gone. I found 14" alder, S.50°45'E., 10ft. with illegible scribe marks 7ft. above the ground. Found 18" alder, N.40°45'W., 9ft. with healed witness face of which I never chopped open. I set a cedar post 24" above ground Mkd.  $\frac{1}{4}$ S9 on West and  $\frac{1}{4}$ S10 on east sides and mark 2 new BTs;  
 45" cedar snag 50ft. tall leaning to the south, N.82°E. 27ft. Mkd.  $\frac{1}{4}$ S10 BT.  
 36" spruce, N.2°W., 46ft. Mkd.  $\frac{1}{4}$ S9 BT.

by Mervin Whitmore,  
 Tillamook Co. deputy surveyor  
 3-23-61

T4SR9W

17	16
20	21

Section corner to sections 16-17-20-21

I found the original cedar post lying upon the ground with a squared top but no visible scribing. A 20x16x6 in. stone lies at base of post. The original Monument was a cedar post 5ft. long.

Original Witnesses:

- 8" alder., N.35°30'E., 24 Lks., Mkd. T4SR9WS16 BT.
- 12" alder, S.48°E., 17 lks. Mkd. T4SR9WS21 BT.
- 14" alder, S.57°30'W., 18 $\frac{1}{2}$  Lks. Mkd. T4SR9WS20 BT
- 6" alder, N.56°W., 44Lks. Mkd. T4SR9WS17 BT

I found 18" alder N.35°30'E., 16ft. with visible Mks.; T4SR9WS16. Found the SW and SE BTs in their recorded bearings and distances. These are now sawed off stumps in a logged off area. I set 1 $\frac{1}{2}$ " pipe 2ft. above ground on south side of the 20x16x6 stone.

I marked 2 new BTs:

- 30" Spruce, N.6°W., 42 $\frac{1}{2}$ ft. Mkd. T4sR9WS 17BT
- 24" Spruce, N.33°E., 73ft. Mkd. T4SR9WS 16BT

No SW or SE witness trees are suitable to mark. Corner is located on a south slope 30ft. West in a logging.