

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner common to Sections 17 and 18,  
Township 1 South, Range 9 West, W. M., Tillamook  
County, Oregon.

ORIGINAL

Post (missing) from which a:

- 32" Hemlock bears S 76 W 18 lks.; now 40" stump, scribe 1/4  
remaining on rotted face.
- 12" Hemlock bears N 49 E 39 lks.; missing.

RESTORATION BY County Surveyor in 1893.

Post (missing) from which a:

- 40" Spruce bears N 9 E 27 lks.; now 45" stump, outer edge of  
face remaining, scribes rotted away.
- 32" Hemlock bears S 76 W 18 lks.; (see original).

RESTORED

Var 21½ E


Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY 1/4 S18 S17 1967 RS 707",  
33 inches in ground, near West edge of power line clearing,  
and from which a:

- 18" Hemlock bears S 61½ W 60.5 ft. from face; scribed 1/4 S18  
BT RS 707.
- 19" powerline pole bears N 49½ E 24.5 ft. from face; scribed  
1/4 S17 BT (West pole of two).


Set 4" x 4" x 50" white painted Cedar post 1.0 feet NE of corner  
pipe. Oregon State Forestry Department metal location poster on  
19" power pole.

Dated August 25, 1967.

Restored by



*Harold Russell*



Present and witnessed by C. Curl  
B. Harris