

CHAINS

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 7, 12, 13, and 18,  
Township 1 South, Ranges 9 & 10 West, W. M., Tillamook  
County, Oregon.

ORIGINAL

Post (missing) from which a:

- 8" Hemlock bears N 57 E 28 lks.; now 10" badly rotted stub,  
scribe BT remaining.
- 4" Hemlock bears N 41 W 19 lks.; missing.
- 24" Hemlock bears S 22 W 9 lks.; now 30" rotted stub 6' high,  
scribes BT, rest rotted away.
- 16" Hemlock bears S 46 E. 75 lks.; missing.

RESTORATION by W. E. Anderson, County Surveyor, 1949.

2 1/2" I P (now in place) from which a:

- 18" Alder bears S 74 1/2 W 27.3 ft.; now 22" stump, scribes TCS  
visible on mostly grown over face.
- 12" Spruce bears N 22 W 31.6 feet.; now 23", face and scribes  
completely grown over.

RESTORED

Var 21 1/2 E


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON  
STATE BOARD OF FORESTRY TLS R9W RLOW S7 S12 S13 S18 1966 RS  
707", 33 inches in ground, inside of 2 1/2" iron pipe set by  
County Surveyor, and from which a:

- 23" Spruce (Co. Sur.) bears N 22 1/4 W 31.0 ft. from face; scribed  
TLS RLOW S12 BT RS 707.
- 6" Spruce bears N 35 3/4 E 7.0 ft. from face; scribed TLS R9W S7  
BT.
- 11" Spruce bears S 71 1/4 E 49.7 ft. from face; scribed TLS R9W S18  
BT.


Set 4" x 4" x 50" white painted Cedar post 1.0 ft. SW of corner pipe.  
Oregon State Forestry Department metal location poster on 6" Spruce  
BT.

Dated August 24, 1967.

Restored by



*Harold Russell*



Present and witnessed by C. Curl  
B. Harris