

# County Surveyor's Record, Tillamook County, Oregon


## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

(Reference FSH 5681.65)

History of original corner establishment:

This corner was established in 1882 by General Land Office (William P. Wright, surveyor)

It was reestablished in 1956 by John C. Carlich (ORLS 287)



Description of corner evidence found:

Found 1½ inch by 48 inch iron pipe for the section corner of 15, 16, 21, 22 from which:

A spruce stump, 38 inches in diameter bears N29½E, 19.0 feet distance

A hemlock stump, 46 inches in diameter bears S51E, 14.2 feet distance

Description of monument and accessories established to perpetuate the original location of this corner

At the corner point set a 2 inch by 30 inch cement filled iron pipe with a brass cap marked

T5S R10W

16	15
21	22

1968

ORLS 650

No BT's were marked in Sections 16 or 21 due to lack of material

Deposited iron pipe beside the monument

U.S.F.S bearing trees signs were placed on all BT's facing the monument

Office of County Surveyor County of Tillamook  
 State of Oregon, I hereby certify that the within instrument was filed in this office  
 for record on the 1st day of August, 1968 at 2 o'clock P.m., (signed)  
John C. Carlich by \_\_\_\_\_  
 (COUNTY OFFICIAL) (DEPUTY)



BOOK 31